

# Oil Field Environmental Incident Summary

**Incident:** 20140103111026      **Date/Time of Notice:** 01/03/2014 10:53

**Responsible Party:** Key Energy Services, LLC

**Well Operator:** HRC OPERATING, LLC

**Well Name:** PETRO-HUNT 157-100-1C-1-1SWD

**Field Name:** DUBLIN

**Well File #:** 90155

**Date Incident:** 1/3/2014

**Time Incident:** 0025

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 157

**Rng:** 100

**Sec:** 1

**Qtr:**

**Location Description:**

**Submitted By:** Daniel Gibson

**Received By:**

**Contact Person:** Daniel Gibson  
1801 CALIFORNIA STREET  
SUITE 3500  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0	barrels	0	barrels		
<b>Brine</b>	0	barrels	0	barrels		
<b>Other</b>	5	barrels	4	barrels		

**Description of Other Released Contaminant:**

produced water

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None.

**Areal Extent:**

**Potential Environmental Impacts:**

Impact to shallow surface soils

**Action Taken or Planned:**

Free fluids were recovered using 12 bags of absorbent material.

**Wastes Disposal Location:** At this time I believe the recovered material will be collected and transported to a Key Energy facility for disposal through Safety Kleen.

**Agencies Involved:**

**Updates**

---

**Date:** 1/3/2014      **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.